

WPR23LA001

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of nose down airplane in a river (Courtesy of law enforcement officer)



Photograph 2 - View of nosed down airplane in a river with damage to left bi-wing and empennage (Courtesy of law enforcement officer)



Photograph 3 - Photo of power pole and line in relation to accident airplane prior to impact with added depiction of the power line over the river (courtesy of witness)



Photograph 4 - Map depiction of wreckage site in relation to power lines