



Photo 1 – Front view of accident airplane (photo courtesy of the pilot)



Photo 2 – View of forward fuselage damage



Photo 3 – View of left wing during exam



Photo 4 – View of right wing during exam



Photo 5 – Left side view of empennage during exam



Photo 6 - Right side view of empennage during exam