

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Tucson State: AZ
ZIP: 85735 Country: USA
Latitude: 32-08-31N Longitude: 111-10-28W
(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 10/15/2022 Local Time: 12:00
mm/dd/yyyy
Time Zone: Pacific

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N7746Y

Manufacturer: Piper

Model: Twin Comanche

Serial Number: 30-837

Year of Manufacture: 1965

Amateur-Built: ☐ Yes ☒ No
If Yes: ☐ Kit Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 3720 lbs

Weight at Time of Accident/Incident: 3270 lbs

Number of Seats: 4 Flight Crew Seats: 1

Cabin Crew Seats: 0 Passenger Seats: 3

Number of Engines: 2

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☒ Retractable

- ☒ Tricycle ☐ Tailwheel
- ☐ Amphibian ☐ High Skid
- ☐ Emergency Float ☐ Skid
- ☐ Float ☐ Ski
- ☐ Hull ☐ Ski Wheel
- ☐ Other Launch Recovery System
- ☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
- ☐ Turbo Shaft ☐ Solid Rocket
- ☐ Turbo Prop ☐ Hybrid Rocket
- ☐ Turbo Jet ☐ None
- ☐ Turbo Fan ☐ Unknown
- ☐ Electric

Fuel System Type (Reciprocating)

- ☐ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Serial	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	LYCOMING	I0320-B1A	L 1768-55A	1965	160	6113	18	1482
Eng. 2	LYCOMING	I0320-B1A	L 1787-55A	1965	160	6113	18	1236
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
- ☐ AAIP ☐ Conditional Inspection
- ☒ Annual ☐ Unknown

Date Last Inspection: 06/23/2022
mm/dd/yyyy

Airframe Total Time: 6113 hrs

hours measured at (Select one)

☒ Last Inspection ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
- ☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
- ☒ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: Hartzell

Model: HC-E2YL-2BSF/F7663D-4

Propeller 2

- ☐ Fixed Pitch
- ☒ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: Hartzell

Model: HC-E2YL-2BSF/F7663D-4

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☒ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☒ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☒ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☒ Autopilot
- ☐ Data Recorder
- ☐ Electronic Flight Bag or Handheld Device
- ☒ Electronic Multifunction Display
- ☐ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☐ Onboard Weather
- ☐ Satellite Tracking Device
- ☒ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Robert I. SnowCity: New CaneyState: TX ZIP: 77357Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437

☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial

☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International

☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Ryan AirportDistance From Airport Center: LRN smAirport Identifier: KRYNDirection From Airport: N/A degrees trueProximity to Airport: ☐ Off Airport Airstrip ☒ On Airport Airstrip ☐ N/AAirport Elevation: 2419 ft. msl**Runway Information**Runway ID: 6L (L/R/C) Length: 4900 ft Width: 75 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure Clearance ☒ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR TVOR ☐ ILS ☐ ASR ☐
☐ VOR DME ☐ Localizer Only ☐ Visual ☐
☐ TACAN ☐ LOC-back course ☐ Contact ☐
☐ RNAV ☐ Circling ☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☒ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying
☒ Yes
 ☐ No

"Flight Crewmember 1" Identification

First Name: Robert City of Residence: New Caney
 Middle Initial: I State: TX ZIP: 77357
 Last Name: Snow Country: USA

Age at time of Accident/Incident: 69 Date of Birth: [REDACTED] mm/dd/yyyy

Certificate Number: [REDACTED]

Degree of Injury

☒ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☒ Left
 ☐ Front
 ☐ Unknown
☐ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☒ Flight Instructor
 ☐ Commercial
 ☐ US Military
☐ Private
 ☐ Recreational
 ☒ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
☒ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☐ Class 1
 ☐ Driver's License (Sport Pilot only)
☒ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
☒ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

03/22/2022
 mm/dd/yyyy

Medical Certificate Limitations

MUST possess Glasses

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

12/30/2021
 mm/dd/yyyy

Flight Review Aircraft

Make: Piper
 Model: PA30

Airplane Rating(s)

(Check all that apply)
☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)
☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)
☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)
☐ None
☒ Airplane Single-Engine
☒ Airplane Multi-Engine
☐ Gyroplane
☐ Powered Lift
☒ Instrument Airplane
☐ Instrument Helicopter
☐ Helicopter
☐ Glider
☐ Sport

Type Ratings

BE350 PIC
LR45 SIC
C560 SIC

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)

	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	11005	642	6405	4376	994	698	224			
Pilot in Command (PIC)	9080	642	6200(APX)	4340(APX)	980(APX)	698	224			
Time as Instructor	3209		3209	0						
This Make Model					30.5	90.4	14.3			
Last 90 Days	22.9	17.7	5.2	17.7	0	1.2				
Last 30 Days	16.9	11.7	5.2	11.7	0	.6				
Last 24 Hours	5.8	5.8		5.8		.6				

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)

Crew Name and Address	Seat Occupied	Injury
First Name: <u>Robert</u> City of Residence: <u>New Caney</u> Middle Initial: <u>I</u> State: <u>TX</u> ZIP: <u>77357</u> Last Name: <u>Snow</u> Country: <u>USA</u>	☒ Left ☒ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Pilot Certificate(s) (Check all that apply) ☐ None ☒ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☒ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer	Restraint Type: Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☒ 3-point ☒ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident Incident Aircraft? ☐ Yes ☒ No	Total Flight Time at the Time of this Accident/Incident: <u>11005</u> hrs	

Crew Name and Address	Seat Occupied	Injury
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____	☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer	Restraint Type: Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident Incident Aircraft? ☐ Yes ☐ No	Total Flight Time at the Time of this Accident/Incident: _____ hrs	

PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)

Name and Address	Seat	Injury	Restraint Type	Inflatable Restraints	Age
First Name: <u>Maria</u> City: <u>New Caney</u> Middle Initial: <u>G</u> State: <u>TX</u> ZIP: <u>77357</u> Last Name: <u>Snow</u> Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☒ Right ☐ Unknown Row: <u>1</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☒ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point

Airport ID: KODO
City: ODESSA
State: TX
Country: USA

Time of Departure

Time: 10:30
Time Zone: Central

Destination

Airport ID: KRYN
City: Tucson
State: AZ
Country: USA

Type Flight Plan Filed

☐ None ☐ VFR IFR
☐ Company VFR ☒ IFR
☐ Military VFR ☐ Unknown
☐ VFR
Activated? ☒ Yes ☐ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

☐ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☐ VFR ☒ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☒ Class D ☐ Prohibited Area ☐ TRSA
☐ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence:

surface ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☒ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV Radio ☐ Internet
☐ Automated Report ☐ None
☒ Commercial Weather Service (DUATS) ☐ Unknown
☒ On-Board Weather

Weather Observation Facility

Facility ID: _____
Observation Time: _____
Time Zone: _____
Distance from Accident Site: _____ nm
Direction from Accident Site: _____ degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Temperature: _____ (C) or _____ (F)

Dew Point: _____ (C) or _____ (F)

Altimeter Setting: _____ in Hg
or _____ MB

Lowest Cloud Condition Height

_____ ft agl

Ceiling Height

_____ ft agl

Wind Direction

☒ Variable

-or-
Direction: _____ degrees true

Wind Speed

☐ Calm
☒ Light and Variable

-or-
Speed: _____ kts

Wind Gusts

☒ Not Gusting

-or-
Speed: _____ kts

Visibility unlimited miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

☒ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

Amount Type
☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Icing Actual

Amount Type
☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Turbulence

Type (Check all that apply) Severity
☒ None ☐ Light
☐ Clear Air ☐ Moderate
☐ Terrain-Induced ☐ Severe
☐ Convective Turbulence ☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☐ Minor ☒ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property (Use additional sheet if necessary)

Aircraft departed the paved runway. Ruts in the grass show that the landing gear did not collapse until the last thirty feet before the plane came to a stop. The props were bent, the landing gear bent upward against the wings and fuselage, the gear doors bent and scratched and I noticed some wrinkling on the left wing, possibly indicating a damaged spar. Oil was leaking from under the right engine.

NARRATIVE HISTORY OF FLIGHT (Please type or print in ink)

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

We departed Conroe, Texas (KCXO) and stopped in Odessa Texas (KODO). At Odessa we topped all six fuel tanks. The flight was normal until short final at the final destination (Tucson Arizona; KRYN). At 300-400 feet there was a strong yaw to the right. I discounted asymmetric thrust from a failed engine because the power was already near idle. That left a control/structural failure as the only other possible cause and I became convinced that this is what had happened. In retrospect that seems unlikely; unless one flies into a thunderstorm structural failure is so rare as to be discounted. At the time, seconds from touchdown, there was no time to consider alternatives. I briefly considered going around to sort things out. But it occurred to me that catastrophic failure could be seconds away. Despite the control problems we were upright and a level, obstruction-free landing area (the airport) was just ahead. I was still struggling with the controls when we touched down. The aircraft exited the runway to the right. The landing gear remained intact until the last thirty feet, then the plane slid to a halt. There was no fire and no parts broke off.

Airport personnel and a representative from the local FBO (Velocity Air) arrived within minutes. An ambulance and fire truck arrived soon after. My wife and I had received no injuries. Ninety minutes later a crane and flatbed arrived to remove the wreckage. I assume airport personnel called them.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

I have gone over the accident in my mind 100 times since it happened. At the time there were only seconds to think and once I convinced myself that I was experiencing a control/structural failure my mind locked down and did not consider any alternative. Since then it has become clear in my mind that there was no structural failure and that the right engine failed.

The first thing any multi-engine pilot thinks when experiencing an uncommanded yaw is engine failure. I discounted this because with the engines near idle there could be no asymmetrical thrust. What did not occur to me is that with the engine failed and the props forward for landing there would be asymmetrical drag.

As you know in multi-engine training most or all of engine emergencies are done in the worst case scenario; full power on climb out. I have done dozens of these both in my initial and yearly (Kingair) simulator training. I have also flown full instrument approaches with a simulated feathered engine. If my emergency in Tucson had been either of these scenarios I would have known exactly what had happened and how to respond.

I have never had an engine cut during the approach to landing. My recommendation to the NTSB is to encourage multi-engine instructors to include at least one of these during training so that the student knows what it feels like. Would it have made a difference in my case? I can't say for sure. Things were happening fast. But if I had been trained to know that asymmetrical drag can be significant I might have recognized the situation sooner and perhaps reacted differently.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction Failure? ☐ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Unknown; Probable Right engine failure.

Total Time/Cycles
On Part

_____ Hours

_____ Cycles

Time Since This Part
Inspected Overhauled

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff

(Convert from pounds, as necessary)

114

Gallons

Fuel Type

☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☒ Yes ☐ No

Method of Exit - Describe how the occupants exited and how many occupants evacuated each location

Door

OTHER AIRCRAFT - COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed☐ Minor☐ Substantial☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

10/30/2022
mm/dd/yyyyName of Pilot/Operator: Robert I. Snow

Signature: _____

-- or -- ☐ Check here to electronically sign this document**If a Person Other than Pilot/Operator is Filing Report**

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document**FOR NTSB USE ONLY**NTSB Accident/Incident No.
WPR23LA013Reviewed by NTSB Regional Office
WPRName of Investigator
D. BakerDate Report Received
10/30/2022