



Photo 1 – View of right main landing gear mark from runway excursion (courtesy of FAA)



Photo 2 – Right main landing gear in foreground and main wreckage in background (courtesy of FAA)



Photo 3 – Left aileron (courtesy of FAA)



Photo 4 – Left horizontal stabilizer and elevator (courtesy of FAA)



Photo 5 – Right main landing gear support assembly (Courtesy of FAA)




Photo 6 – Right main landing gear support assembly with fractured bolt (courtesy of FAA)