



Photo 1 – Accident Site (FAA Photo)



Photo 2 – Wreckage at Storage Facility



Photo 3 – No. 1 Cylinder Spark Plugs




Photo 4 - No. 3 Cylinder Bottom Spark Plug Debris (FAA Photo)



Photo 5 - No. 1 Piston with embedded Exhaust Valve and Crack



Photo 6 - No. 1 Cylinder Interior



Photo 7 – No. 3 Piston