



Photo 1 – View of substantial damage to belly (photo courtesy of pilot)



Photo 2 – View of substantial damage to belly (photo courtesy of pilot)