



Photo 1 – View of Fuselage, Tail Boom and Horizontal Stabilizer Damage (Courtesy of Pilot)



Photo 2 – View of Horizontal Stabilizer and Rudder Damage (Courtesy of FAA)



Photo 3 – View of Nose Strut Damage (Courtesy of FAA)



Photo 4 – View of Nosewheel and Rotor Runway Markings (Courtesy of FAA)