

WPR23LA149

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane from the right. (Courtesy of Morgan County Sherriff's Department.)



Photograph 2 - View of airplane cabin area. (Courtesy of Morgan County Sherriff's Department.)



Photograph 3 - View of airplane from forward. (Courtesy of Morgan County Sherriff's Department.)



Photograph 4 - The propeller assembly. (Courtesy of Morgan County Sherriff's Department.)



Photograph 5 - Propeller attachment bolts. (Courtesy of Morgan County Sherriff's Department.)