

WPR23LA175

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Side View of Accident Airplane (Courtesy of Law Enforcement)



Photograph 2 - Right Side View of Airplane (Courtesy of Law Enforcement)



Photograph 3 - Left Side View of Airplane (Courtesy of Law Enforcement)



Photograph 4 - Left Side View of Airplane (Courtesy of Law Enforcement)



Photograph 5 - View of Left Engine (Courtesy of Law Enforcement)