

WPR23LA177

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left wing (Courtesy of the pilot)



Photograph 2 - Right wing (Courtesy of the pilot)



Photograph 3 - Right horizontal stabilizer (Courtesy of pilot)