



Photo 1 – View of Airplane Damage (Source: FAA)



Photo 2 – View of Airplane Damage (Source: FAA)



Photo 3 – View of Airplane Damage



Photo 4 – View of Right Nose Wheel in the Retracted Position



Photo 5 – View of Left Nose Wheel Retracted



Photo 6 – View of Right Main Gear Indicator in the UP Position



Photo 7 – View of Right Main Gear Actuator in the Retracted Position



Photo 8 – View of Left Main Gear Actuator in the Retracted Position