



Photo 1 – View of damage to accident airplane (Courtesy of Law Enforcement)



Photo 2 – View of fuel selector in OFF position (Courtesy of Law Enforcement)