



Photo 1 – View of accident airplane from left wing (courtesy of FAA)




Photo 2 – Throttle linkage on accident airplane




Photo 3 – Mixture control linkage on accident airplane