

WPR23LA201

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to forward right side of the airplane (Courtesy of FAA)



Photograph 2 - View of the damage to both wings (Courtesy of FAA)



Photograph 3 - View of damage to left side of the airplane (Courtesy of FAA)



Photograph 4 - View of damage to the right side of the airplane (Courtesy of FAA)



**Photograph 5 - Google Earth view of distance and direction from runway 11L to accident site
(Courtesy of NTSB)**