



Photo 1 – Left side view of accident airplane (photo courtesy of local law enforcement)



Photo 2 – Front view of accident airplane (photo courtesy of local law enforcement)



Photo 3 – View of cockpit fire damage



Photo 4 – View of airplane engine during examination