

WPR23LA232

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane in Field, Right Side (Courtesy of Pilot)



Photograph 2 - Airplane in Field, Rear View (Courtesy of Pilot)



Photograph 3 - Wreckage at Storage Facility (Courtesy of NTSB)



Photograph 4 - Propeller (Courtesy of NTSB)



Photograph 5 - Spark Plugs (Courtesy of NTSB)



Photograph 6 - Carburetor (Courtesy of NTSB)



Photograph 7 - Fuel Flow Sensors (Courtesy of NTSB)