



Photo 1 – View of left-wing damage (Photo courtesy of Pilot)



Photo 2 – View of right-wing damage (Photo courtesy of Pilot)