



**Photo 1 – View of damage to left wing and wing strut (provided by pilot)**



**Photo 2 – View of damage to right wing strut, vertical stabilizer, and rudder (provided by pilot)**