

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Deer Park State: WA
 ZIP: 99006 Country: USA
 Latitude: 47-58-01.397N Longitude: 117-25-42.912W
(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 07/07/2023 Local Time: 0830
mm/dd/yyyy
 Time Zone: PDT

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☐ None

AIRCRAFT INFORMATION

Registration Number: 633VS

Manufacturer: Vickers-Armstrong

Model: Spitfire Mk IXe

Serial Number: CBAF IX.571

Year of Manufacture: 1944

Amateur-Built: ☐ Yes ☒ No
 If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 7,500 lbs

Weight at Time of Accident/Incident: 6,430 lbs

Number of Seats: 1 Flight Crew Seats: 1

Cabin Crew Seats: 0 Passenger Seats: 0

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate (Check all that apply)

- | Standard | Special |
|------------------------------------|---|
| ☐ Normal | ☐ Restricted |
| ☐ Aerobatic | ☐ Limited |
| ☐ Balloon | ☐ Provisional |
| ☐ Commuter | ☐ Special Flight |
| ☐ Transport | ☒ Experimental |
| ☐ Utility | ☐ Special Light-Sport |
| | ☐ Experimental Light-Sport |
- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

- ☐ Retractable
- | | |
|--|---|
| ☐ Tricycle | ☒ Tailwheel |
| ☐ Amphibian | ☐ High Skid |
| ☐ Emergency Float | ☐ Skid |
| ☐ Float | ☐ Ski |
| ☐ Hull | ☐ Ski/Wheel |
- ☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- | | |
|--|-------------------------------------|
| ☒ Reciprocating | ☐ Liquid Rocket |
| ☐ Turbo Shaft | ☐ Solid Rocket |
| ☐ Turbo Prop | ☐ Hybrid Rocket |
| ☐ Turbo Jet | ☐ None |
| ☐ Turbo Fan | ☐ Unknown |
| ☐ Electric | |

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. <i>mm dd yyyy</i>	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Rolls-Royce Packard	Merlin 266	V-324405	not known	1760	not known	1	25
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 06162023
mm/dd/yyyy

Airframe Total Time: 1,386.8 hrs
 hours measured at (Select one)
☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☒ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
☒ Controllable Pitch
☐ Ground Adjustable

Manufacturer: Dowty Rotol

Model: R12-4F5-4

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☐ Yes ☒ No

If Yes:

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☐ Yes ☒ No

Was ELT still connected to antenna? ☐ Yes ☒ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☒ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☐ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**

Name: FWF, Ltd. (for Historic Flight Foundation)

City: [REDACTED]

State: WA

ZIP: 99212

Fractional Ownership Aircraft: ☐ Yes ☒ No

Country: USA

Operator of Aircraft☒ Same As Registered Owner☐ Same Address as Registered Owner

Name: FWF, Ltd.

City: _____

Doing Business As: _____

State: _____

ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437

- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial

☐ Public Aircraft (Select one)

- ☐ Armed Forces
☐ Federal
☐ State
☐ Local

☐ Unknown**Revenue Operation for FAR 121, 125, 129, 135**

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International

- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☒ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)

Airport Name: Deer Park

Airport Identifier: DEW

Proximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/A

Distance From Airport Center: 0 sm

Direction From Airport: 0 degrees true

Airport Elevation: 2,211 ft. msl

Runway Information

Runway ID: 16 (L/R/C) Length: 6,100 ft Width: 75 ft

Runway/Landing Surface (Check all that apply)

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☒ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Crosswind ☐ Aborted Landing (after touchdown)
☐ Unknown

IFR Approach (Check all that apply)☒ None

- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)☒ None

- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)							
Crew Name and Address First Name: <u>N/A all</u> City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____				Seat Occupied ☐ Left ☐ Center ☐ Right ☐ Front ☐ Rear ☐ Single ☐ Unknown		Injury ☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer				Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs					
Crew Name and Address First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____				Seat Occupied ☐ Left ☐ Center ☐ Right ☐ Front ☐ Rear ☐ Single ☐ Unknown		Injury ☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer				Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs					
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)							
Name and Address		Seat	Injury	Restraint Type		Inflatable Restraints	Age
First Name: <u>N/A all</u> City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point

Airport ID: SFF

City: Spokane

State: WA

Country: USA

Time of Departure

Time: 0800

Time Zone: PDT

Destination

Airport ID: DEW

City: Deer Park

State: WA

Country: USA

Type Flight Plan Filed

- ☒ None ☐ VFR/IFR
☐ Company VFR ☐ IFR
☐ Military VFR ☐ Unknown
☐ VFR

Activated? ☐ Yes ☐ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

- ☒ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☒ VFR ☐ IFR ☐ VFR On Top ☒ Traffic Advisory ☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

- ☐ Class A ☐ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☒ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence: _____ ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

- ☒ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV/Radio ☐ Internet
☐ Automated Report ☐ None
☐ Commercial Weather Service (DUATS) ☐ Unknown
☐ On-Board Weather

Weather Observation Facility

Facility ID: Checked DEW weather from SFF

Observation Time: _____

Time Zone: _____

Distance from Accident Site: _____ nm

Direction from Accident Site: _____ degrees true

Basic Conditions

- ☒ VMC
☐ IMC
☐ Unknown

Light Condition

- ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

- ☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

_____ ft agl

Ceiling

- ☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

_____ ft agl

Temperature: _____ (C) or _____ (F)

Dew Point: _____ (C) or _____ (F)

Altimeter Setting: _____ in. Hg
or _____ MB

Wind Direction

☐ Variable

-or-

Direction: 070 degrees true

Wind Speed

- ☐ Calm
☒ Light and Variable

-or-

Speed: 6 kts

Wind Gusts

☐ Not Gusting

-or-

Speed: _____ kts

Visibility 20 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: 2,400+ ft

Intensity of Precipitation

- ☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

- ☒ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

- ☒ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

Amount

- ☒ None
☐ Trace
☐ Light
☐ Moderate
☐ Severe
☐ Unknown

Type

- ☐ N/A
☐ Rime
☐ Clear
☐ Mixed
☐ Unknown

Icing Actual

Amount

- ☒ None
☐ Trace
☐ Light
☐ Moderate
☐ Severe
☐ Unknown

Type

- ☐ N/A
☐ Rime
☐ Clear
☐ Mixed
☐ Unknown

Turbulence

Type (Check all that apply)

- ☒ None ☐ Light
☐ Clear Air ☐ Moderate
☐ Terrain-Induced ☐ Severe
☐ Convective Turbulence ☐ Extreme

Severity

- ☐ Light
☐ Moderate
☐ Severe
☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Prop strike
Damaged prop blades and spinner
Creases to engine cowling
Collapsed gear
Oil tank dented
Scrapes on starboard wing
The wing ribs and gear trunnions appear to be OK
The starboard wingtip (non-structural wood) will need to be replaced

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

On Friday, July 7, 2023, I flew a Supermarine Spitfire Mk. IXe, N633VS, on an inspection check flight from Spokane Felts Field (KSFF) to Deer Park Airport, Deer Park Washington. Prior to departing KSFF, I checked weather at DP. There was no significant weather or NOTAMS. Winds were reported at 6 mph out of the east.

Initial climb-out and a circuit around the tower to check landing gear were uneventful. Systems checks were made in the short en route segment to DP. I assessed conditions and called an overhead approach to RW 16.

The landing was normal through the touch-down and early roll-out. The Spitfire uses air for brakes and flaps. The tail wheel is not connected to the rudders at all (it is free casting). My normal scan before landing is to always check brake pressure, which I did on downwind. The brake pressure was full. After touch-down the aircraft had a slight drift to the left, which is normal for the plane to have a slight drift to the left or the right. To steer the aircraft once the tailwheel is down you must use a combination of rudder and brakes. While applying air to activate the brakes the plane pulled to the left. I squeezed the air activation lever (mounted at the top of the spade/stick) and depressed the right rudder pedal. However, I could not return the aircraft to the center of the runway. The aircraft continued drifting to the left and exited the runway. The Spitfire is very nose-heavy due to the Merlin engine. When the aircraft reached the dirt surface adjacent the runway, it turned forward onto the propeller. The gear collapsed but the plane came to rest without scratching the two radiator boxes. There were no injuries.

Tire tracks on the runway indicate the starboard brake may have locked, substantially reducing its braking action.

I was assisted by the fire department, the sheriff and experienced salvage professionals from a local company. An FAA investigator traveled to the scene. I spoke with a representative of NTSB by telephone. She released the aircraft to storage. The aircraft was moved over several hours without sustaining further damage. The impromptu crew did a good job.

As to damage, the wooden propeller blades and the spinner were destroyed but the actual propeller mechanism appears to be undamaged. Pieces of the engine cowl were creased. We have pictures to offer of the wing ribs and gear trunnions. They seem to be undamaged. The tip of the starboard wing was damaged but the last rib (structural element) appears to be undamaged. During WWII the tips of Spitfires were sometimes removed to increase the roll rate in combat. The outboard-most rib would be cuffed. The tip itself is built around wood. The engine will need to be removed, inspected and tested. Often, the wooden propeller blades save the crankshaft by absorbing the stress. What remains of the propeller can be turned by hand suggesting the crankshaft is not bent.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

When repaired, check brakes for any tendency to lock. Check the shuttle valve for proper distribution of air pressure to port and starboard brakes. The shuttle valve regulates air pressure from the engine pump to the landing gear/brakes.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Brake lock, starboard brake. The shuttle valve was inspected when the aircraft was restored in 2011.

Total Time/Cycles
On Part

_____ Hours

300 _____ Cycles

Time Since This Part
Inspected/Overhauled

160 _____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff

(Convert from pounds, as necessary)

87 (full main tanks) _____ Gallons

Fuel Type

☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☐ Yes ☒ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

I turned off the fuel master, the mags and the battery, slid back the canopy, released my belts (I was upright) and slid down the wing.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for *other* aircraft)

Aircraft Registration Number

N/A

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed☐ Minor☐ Substantial☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report <u>07/22/2023</u> mm/dd/yyyy	Name of Pilot/Operator <u>John T. Sessions</u> Signature: <u>[Redacted]</u> — or — ☐ Check here to electronically sign this document
--	---

If a Person Other than Pilot/Operator is Filing Report

Name: _____	Title: _____
Signature: _____	
— or — ☐ Check here to electronically sign this document	

FOR NTSB USE ONLY

NTSB Accident/Incident No. WPR23LA268	Reviewed by NTSB Regional Office WPR	Name of Investigator Paul Rho	Date Report Received 7/22/2023
---	--	---	--