

WPR23LA272

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Forward View of Airplane Wreckage (Courtesy of Pilot)



Photograph 2 - Wreckage, Left Side (Courtesy of Pilot)

Fuel Fitting Thread Abrasion Damage



Photograph 3 - Fuel Line Fitting Damage (Courtesy of NTSB)



Photograph 4 - Fuel Line Fitting (Courtesy of NTSB)