



Tealeye Cornejo
Air Safety Investigator (Field)
AS-WPR

Date: September 8, 2023
Subject: WPR23LA312, Damage Description
Contact: Tracy Van Iwarden, Pilot

According to Mr. Van Iwarden, prior to his phone battery died he was able to take a photo of the right side of the airplane. He stated that his phone was in screen saver mode so he could barely see what he was photographing. The picture shows no structural damage to the right wing; however, he stated that the left-wing and strut were damaged.