



Photo 1 – Left view of airplane with substantial damage to left wing (Photo courtesy of LEO)



Photo 2 – Front view of airplane with fuselage damage (Photo courtesy of LEO)



Photo 3 – Rear view of airplane with empennage damage (Photo courtesy of LEO)