

WPR23LA329

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Forward view of wing damage (Courtesy of pilot)



Photograph 2 - View of left wing damage (Courtesy of pilot)



Photograph 3 - View of wing damage, left rear (Courtesy of pilot)



Photograph 4 - View of tire marks on airport perimeter road (Courtesy of pilot)