

WPR23LA341

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane's left wings damage as viewed from the rear. (Courtesy of Airport Operations)



Photograph 2 - Airplane's right wing damage as viewed from the front. (Courtesy of Airport Operations)