



Photo 1 – View of right wing damage (photo courtesy of the witness)



Photo 2 - View of right horizontal and elevator damage (photo courtesy of the witness)