

PHOTOGRAPHS



Figure 1: Airplane at Accident Site



Figure 2: Right Wing with Hole from Landing Gear