

WPR23LA367

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of Left Side of Damaged Airplane (Courtesy of FAA)



Photograph 2 - Close-up View of Damaged Left Wing (Courtesy of FAA)



Photograph 3 - Rear View of Damaged Left Horizontal Stabilizer (Courtesy of FAA)



Photograph 4 - Front View of Damaged Left Horizontal Stabilizer (Courtesy of FAA)