

WPR24FA035

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane against a tree



Photograph 2 - View of airplane at examination



Photograph 3 - View of engine and propeller




Photograph 4 - View of removed wings



Photograph 5 - View of top spark plugs removed



Photograph 6 - View of no. 2 & 4 cylinders



Photograph 7 - View of no. 1 & 3 cylinders



Photograph 8 - View of removed magnetos



Photograph 9 - View of Carburetor Bowl