


WPR24FA123

INVESTIGATION PHOTOGRAPHS



Photograph 1 - The airplane at rest in the rice paddy, viewed from aft right.



Photograph 2 - The fuel gauge and tank switch.



Photograph 3 - The airplane's propeller.