

[WPR24FA132]


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage



Photograph 2 - Tail Rotor Blades



Photograph 3 - Turbine to Compressor Mating Spline



Photograph 4 - Fractured Turbine to Compressor Coupling Shaft