

WPR24FA185

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the accident airplane shortly after impact before first responder occupant extrication, showing damage to the right wing (Courtesy of social media)



Photograph 2 - View of the northeast face of Picacho Peak with the wreckage just below the summit




Photograph 3 - Aerial view from northeast to southwest and wreckage just below the summit



Photograph 4 - Google Earth view from the southwest showing Picacho Peak ridgeline



Photograph 5 - View of impact damage to the nose section of the airplane



Photograph 6 - Southeast to northwest view of the wreckage and impact damage to lower fuselage and nose section