

WPR24FA190

ON SCENE INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main wreckage from rear.



Photograph 2 - Main wreckage, cabin.



Photograph 3 - Engine at accident site.



Photograph 4 - Propeller assembly.



Photograph 5 - Outboard portion of left wing with aileron attached.