

Tealeye Cornejo
Air Safety Investigator (Field)
AS-WPR

Date: August 5, 2025

Subject: WPR24FA195 - Photos taken during the flight

The following photos and locations were provided by a family member of the passenger. The photos were accompanied by GPS locations of where the photos were taken.




Figure 1: Plot of Image Locations




Figure 2: Plot of 3 images near the accident site.



Figure 3: Image "A" - Courtesy of a family member.



Figure 4: Image "C" - Courtesy of a family member.



Figure 5: Image "D" - Courtesy of a family member.



Figure 6: Image "E" - Courtesy of a family member.



Figure 7: Image "F" - Courtesy of a family member.



Figure 8: Image "G" - Courtesy of a family member.



Figure 9: Image "H" - Courtesy of a family member.



Figure 10: Image "I" - Courtesy of a family member.



Figure 11: Image "J" - Courtesy of a family member.



Figure 12: Image "K" - Courtesy of a family member.



Figure 13: Image "L" - Courtesy of a family member.