

WPR24FA215

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N6210A at the accident site.



Photograph 2 - Top view closeup.



Photograph 3 - Top view.



Photograph 4 - Video camera attached to the left wing.



Photograph 5 - N6210A during the go-around (Courtesy of a witness)