

WPR24FA255

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of operating area photographed from USFS airplane the day of the accident showing smoke and haze (Courtesy of USFS)




Photograph 2 - View of operating area, photograph from a SEAT cockpit showing smoke and haze the day of the accident (Courtesy of USFS)



Photograph 3 - View of wreckage layout in a hangar for an examination



Photograph 4 - View of right side of the engine and the rear side of the propeller and hub assembly



Photograph 5 - Google Overlay of ADS-B Flight track, Fire Perimeter, TFR Perimeter in relation to Accident Site, Airport of Operations and Fire Suppression Site.