



Photo 1 – View of helicopter structural damage to airframe (Courtesy of FAA)



Photo 2 – View of helicopter structural damage to vertical and horizontal stabilizer (Courtesy of FAA)



Photo 3 – View of fuel placard above fuel cell (Courtesy of FAA)