

WPR24LA030

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Rear View of Helicopter the Day of the Accident (Courtesy of Pilot)



Photograph 2 - Side View of Helicopter the Day of the Accident (Courtesy of Pilot)



Photograph 3 - Left Side of Helicopter Showing Fire Damaged



Photograph 4 - Left Side View of Transmission Area