

WPR24LA034


INVESTIGATION PHOTOGRAPHS




Photograph 1 - View of the airplane at the accident site. (Courtesy of the FAA.)



Photograph 2 - View of the airplane from the left, with the left engine in foreground. (Courtesy of Textron Aviation.)



Photograph 3 - The right engine and propeller. (Courtesy of Textron Aviation.)



Photograph 4 - The left engine throttle control. (Courtesy of Textron Aviation.)