

WPR24LA039


## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of nosed over airplane with damage to aft fuselage (Courtesy of FAA)**



**Photograph 2 - View of recovered airplane at follow-up examination.**



**Photograph 3. View of fuel dipstick usage exemplar (courtesy of operator).**