

WPR24LA046

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, main wreckage (Courtesy of the Airport Manager)



Photograph 2 - Accident site, main wreckage (Courtesy of the Airport Manager)



Photograph 3 - Accident site, fence damage. (Courtesy of the Airport Manager)



Photograph 4 - Accident site, debris field. (Courtesy of the Airport Manager)



Photograph 5 - Accident site, lower cowling. (Courtesy of the Airport Manager)



Photograph 6 - Accident site, main wreckage uprighted. (Courtesy of the Airport Manager)



Photograph 7 - Accident site, main wreckage relocation. (Courtesy of the Airport Manager)