



Photo 1 – Accident airplane (courtesy of FAA)



Photo 2 – Left seat foot well (courtesy of FAA)




Photo 3 – Damage to engine firewall (courtesy of FAA)