

WPR24LA060

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Forward to aft view of the accident airplane with propeller damage (Courtesy of FAA)



**Photograph 2 - View of the right side of the accident airplane with damage to right wing
(Courtesy of FAA)**



Photograph 3 - View of damage to outboard right wing and leading edge (Courtesy of FAA)



Photograph 4 - Left aft view of the accident airplane (Courtesy of FAA)



Photograph 5 - Right aft view of the accident airplane (Courtesy of FAA)