

WPR24LA066

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane in a field as viewed from the left side. (Courtesy of Byron Airport Operations)



Photograph 2 - Airplane's left wing as viewed from the rear. (Courtesy of Byron Airport Operations)