

WPR24LA068

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane, Left Side (Courtesy of FAA)



Photograph 2 - Left Wing Damage (Courtesy of FAA)



Photograph 3 - Left Aileron (Courtesy of FAA)