

WPR24LA087

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane's tire markings in the grass off the departure end of the runway. (Courtesy of Airport Manager).



Photograph 2 - Airplane's tire markings in the grass leading to where the airplane came to rest. (Courtesy of Airport Manager).



Photograph 3 - Airplane Wreckage as viewed from the front (Courtesy of Airport Manager).