

WPR24LA095

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, left side view of the main wreckage. (Courtesy of Casper Fire)



Photograph 2 - Accident site, forward view of the wreckage. (Courtesy of Casper Fire)



Photograph 3 - Accident site, view of the empennage. (Courtesy of Casper Fire)



Photograph 4 - Accident site, right side view of the wreckage. (Courtesy of Casper Fire)



Photograph 5 - Accident site, view of the right wing. (Courtesy of Casper Fire)