

YEAR
20
DATE

RECORDING
TACH
TIME

TODAY'S
FLIGHT

TOTAL
TIME IN
SERVICE

Description of Inspections, Tests, Repairs and Alterations
Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

Chino Aviation Inc.

7000 Merrill Ave. #33 Hangar A-340 Chino CA 91710

N167U Tach; 2077.1 Total Time: 7855.3 08/18/2023

Inspected this aircraft FAR 43 appendix D checklist for Annual inspection. opened all inspection panels, inspected and lubricated pulleys, removed oxygen bottle and had it hydro tested by Obrien Enterprises and is next due in 5 years, bottle re installed and serviced, replaced TIT gauge with new P.N. 46124, inspected and greased all wheel bearings, serviced brake's reservoir, tested landing gear and systems with airplane on jacks, no defects found. Complied with AD 76-07-12 R1 by inspection and testing of ignition switches and is next due every 100 hours. ELT inspected and tested per FAR91.207 and found airworthy, ELT battery pack BP 1010 is next due August 2024. Replaced sheer pin and chain on main door handle, replaced left cowl flap motor with serviceable part and Tested cowling flap ok.

I certify that this aircraft has been inspected in accordance with an Annual Inspection And found airworthy at this time.

Agustin Cendejas

[Redacted Signature]
