


WPR24LA122

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of airplane (Courtesy of Pilot)



Photograph 2 - View of wheel assembly



Photograph 3 - View of outboard gear spring



Photograph 4 - View of gear spring inboard fracture (wheel-side)



Photograph 5 - View of gear spring inboard fracture (planeside)