

WPR24LA125

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Takeoff with Windsock (Courtesy of R. Webb)



Photograph 2 - Elevator Position on Takeoff (Courtesy of R. Webb)



Photograph 3 - Airplane Wreckage - Right Side (Courtesy of R. Webb)



Photograph 4 - Airplane Wreckage - Front (Courtesy of R. Webb)