

WPR24LA130

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Final Position and Damage (courtesy of pilot)



Photograph 2 - Airplane Final Position and Damage (courtesy of pilot)



Photograph 3 - Airplane Final Position (courtesy of pilot)



Photograph 4 - Airplane Final Position (courtesy of pilot)



Photograph 5 - Airplane Final Position (courtesy of pilot)



Photograph 6 - Fuel Level Post-Accident (courtesy of pilot)



Photograph 7 - Fuel System at Firewall (NTSB photo)



Photograph 8 - Header Fuel Tank, Mid-Fuselage (NTSB photo)